

Emergency Lighting Automated Test Results By Site



Site Code - 00000

Site Name - Nightingale House

Test Type - Floor 0 All types of

Date Range - Tests performed between 01 April 2017 and 30 April 2017

Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 01 Emergency Light 50	Address '50' of 1st KL6811 on panel	22 Apr 2017	04:00	Function Test	Passed
		08 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 51	Address '51' of 1st KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 01 Emergency Light 52	Address '52' of 1st KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 01 Emergency Light 53	Address '53' of 1st KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 01 Emergency Light 54	Address '54' of 1st KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 01 Emergency Light 55	Address '55' of 1st KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 02 Emergency Light 50	Address '50' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 02 Emergency Light 51	Address '51' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 02 Emergency Light 52	Address '52' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 02 Emergency Light 53	Address '53' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed

Emergency Lighting Automated Test Results By Site



Site Code - 00000

Site Name - Nightingale House

Test Type - Floor 0 All types of

Date Range - Tests performed between 01 April 2017 and 30 April 2017

Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 02 Emergency Light 54	Address '54' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 02 Emergency Light 55	Address '55' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 02 Emergency Light 56	Address '56' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 02 Emergency Light 57	Address '57' of 2nd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 03 Emergency Light 50	Address '50' of 3rd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 03 Emergency Light 51	Address '51' of 3rd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 03 Emergency Light 52	Address '52' of 3rd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 03 Emergency Light 53	Address '53' of 3rd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 03 Emergency Light 54	Address '54' of 3rd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 03 Emergency Light 55	Address '55' of 3rd KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed

Emergency Lighting Automated Test Results By Site

Site Code - 00000

Site Name - Nightingale House

Test Type - Floor 0 All types of

Date Range - Tests performed between 01 April 2017 and 30 April 2017



Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 04 Emergency Light 51	Address '51' of 4th KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 04 Emergency Light 52	Address '52' of 4th KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
Dali 04 Emergency Light 53	Address '53' of 4th KL6811 on panel	22 Apr 2017	05:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
		08 Apr 2017	05:00	Function Test	Passed
SITE TOTALS		Tests Passed 47		Tests Failed: 0	

Emergency Lighting Automated Test Results By Site



Site Code - 00001

Site Name - Nightingale House

Test Type - Floor 1 All types of

Date Range - Tests performed between 01 April 2017 and 30 April 2017

Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 01 Emergency Light 50	Address '50' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 51	Address '51' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 52	Address '52' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 53	Address '53' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 54	Address '54' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 50	Address '50' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 51	Address '51' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 52	Address '52' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 53	Address '53' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed

Emergency Lighting Automated Test Results By Site



Site Code - 00001

Site Name - Nightingale House

Test Type - Floor 1 All types of

Date Range - Tests performed between 01 April 2017 and 30 April 2017

Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 02 Emergency Light 54	Address '54' of 2nd KL6811 on panel	04 Apr 2017	04:00	Function Test	Passed
		18 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 55	Address '55' of 2nd KL6811 on panel	04 Apr 2017	04:00	Function Test	Passed
		18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
Dali 02 Emergency Light 56	Address '56' of 2nd KL6811 on panel	04 Apr 2017	04:00	Function Test	Passed
		18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 57	Address '57' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 50	Address '50' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 51	Address '51' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 52	Address '52' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 53	Address '53' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed

Emergency Lighting Automated Test Results By Site



Site Code - 00001

Site Name - Nightingale House

Test Type - Floor 1 All types of

Date Range - Tests performed between 01 April 2017 and 30 April 2017

Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 03 Emergency Light 54	Address '54' of 3rd KL6811 on panel	12 Apr 2017	22:00	Duration Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
		18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 55	Address '55' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		12 Apr 2017	22:00	Duration Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 56	Address '56' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 57	Address '57' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 50	Address '50' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 51	Address '51' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 53	Address '53' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 54	Address '54' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 55	Address '55' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed

Emergency Lighting Automated Test Results By Site

Site Code - 00001

Site Name - Nightingale House

Test Type - Floor 1 All types of

Date Range - Tests performed between 01 April 2017 and 30 April 2017



Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 04 Emergency Light 56	Address '56' of 4th KL6811 on panel	04 Apr 2017	04:00	Function Test	Passed
		18 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 57	Address '57' of 4th KL6811 on panel	04 Apr 2017	04:00	Function Test	Passed
		18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
SITE TOTALS		Tests Passed 65		Tests Failed: 0	

Emergency Lighting Automated Test Results By Site

Site Code - 00002

Site Name - Nightingale Floor 2

Test Type - All types of test

Date Range - Tests performed between 01 April 2017 and 30 April 2017



Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 01 Emergency Light 50	Address '50' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 51	Address '51' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 52	Address '52' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 53	Address '53' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 01 Emergency Light 54	Address '54' of 1st KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 50	Address '50' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 51	Address '51' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 52	Address '52' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 53	Address '53' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 54	Address '54' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed

Emergency Lighting Automated Test Results By Site

Site Code - 00002

Site Name - Nightingale Floor 2

Test Type - All types of test

Date Range - Tests performed between 01 April 2017 and 30 April 2017



Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 02 Emergency Light 55	Address '55' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 56	Address '56' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 02 Emergency Light 57	Address '57' of 2nd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 50	Address '50' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 51	Address '51' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 52	Address '52' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 53	Address '53' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 54	Address '54' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 55	Address '55' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 03 Emergency Light 56	Address '56' of 3rd KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed

Emergency Lighting Automated Test Results By Site

Site Code - 00002

Site Name - Nightingale Floor 2

Test Type - All types of test

Date Range - Tests performed between 01 April 2017 and 30 April 2017



Emergency Light Name	Dali Address	Test Date	Test Time	Test Type	Test Result
Dali 04 Emergency Light 50	Address '50' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 51	Address '51' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 53	Address '53' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
Dali 04 Emergency Light 55	Address '55' of 4th KL6811 on panel	18 Apr 2017	04:00	Function Test	Passed
		04 Apr 2017	04:00	Function Test	Passed
SITE TOTALS		Tests Passed 48			Tests Failed: 0
GRAND TOTALS FOR ALL SITES		Tests Passed 160			Tests Failed: 0